

## Accessories for your pressure measurement devices...





- Hoses
- Connectors for example M10x1, NPT 1/8", Minimess etc.
- Hand-pumps for pressure generation up to 25 bar
- Valves
- Volumes for adjusting fine pressures
- etc.



Please also do ask for our service cases.

Those are available as an accessorie for our Handheld Pressure Gauges in various versions.

## For exapmple:

Hand-pump, with built in variable bellow for positive overpressure up to 5 bar T-connectors, 4/6 mm hose, service case

or

Hand-pump, with built in variable bellow for underpressure up to -750 mbar T-connectors, 4/6 mm hose, service case

